

Zuordnung Regler und Schalter				
Typ Ventilator	Trafo-Drehzahlsteller RDS	Motor-Vollschutzgerät		Polumschalter PDA
		MD	M...	
VARD 225/4	1	X	–	–
VARD 225/2	1	X	–	–
VARD 225/8/4	–	–	3	12*
VARD 225/4/2	–	–	3	12*
VARD 250/4	1	X	–	–
VARD 250/2	2	X	–	–
VARD 250/8/4	–	–	3	12*
VARD 250/4/2	–	–	3	12*
VARD 280/4	1	X	–	–
VARD 280/2	2	X	–	–
VARD 280/8/4	–	–	3	12*
VARD 280/4/2	–	–	3	12*
VARD 315/4	1	X	–	–
VARD 315/2/2	4	–	4	–
VARD 315/8/4	–	–	3	12*
VARD 315/4/2	–	–	3	12*
VARD 355/4	1	X	–	–
VARD 355/8/4	–	–	3	12*
VARD 355/4/2	–	–	–	12*
VARD 400/4	4	X	–	12*
VARD 400/2/2	11	–	4	–
VARD 400/12/6	–	–	3	12*
VARD 400/8/4	–	–	3	12*
VARD 400/4/2	–	–	–	12*
VARD 450/2	–	–	–	FUS 16
VARD 450/4/4	4	–	4	–
VARD 450/12/6	–	–	3	12*
VARD 450/8/4	–	–	–	12*
VARD 450/4/2	–	–	–	25
VARD 500/2	–	–	–	FUS 37
VARD 500/4/4	7	–	4	–
VARD 500/12/6	–	–	3	12*
VARD 500/8/4	–	–	–	12*
VARD 500/4/2	–	–	–	25